



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: September 29, 2006

Supervisor DJH

Mine Name: Bright 1 & 2
Operator Name: 3-H Landscape Products LLC
Scott Holt
2160 East riverside Drive
St George, Utah 84790

Permit number: M/021/030
Date: September 14, 2006
Time: 4:00 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Active

Weather: Clear

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspected the quarries when I was in the area.

Directions to Site:

See previous inspection report

Inspection Summary:

The four quarries within the permit all appear to have been active since my last inspection on October 27, 2005. The operator maintains several stockpiles within the disturbance of the two larger quarries. The areas were GPS'd by Ed Ginouves this spring so I did not feel that it was necessary to duplicate his work at this time. A copy of his GPS map is attached. Pictures of three of the site were taken and are included.

All the disturbed areas within the site appeared stable and there were no environmental or erosion concerns noted.

Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspector's Signature

Doug Jensen

Date: 9/29/06

dj:pb

cc: 3-H Landscape Products LLC
Ed Ginouves, BLM, Cedar City FO UTU- 77247-A2

O:\M021-Iron\M0210030-Bright1&2\Inspections\09142006insp.doc

Mine Number: M0210030
Mine Name: Bright 1 and 2
Township 35 S Range 17 W Section 21-22-27-28 SLBM

Inspection Date Oct. 05, 2005
Map Produced by DKS

Acres Disturbed	13.96
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	1.57

Total Acres Disturbed	15.53
-----------------------	-------

Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend
All items symbolized in legend may not be appear on map

- County Boundary

Township or range line: location doubtful

Section line

Section line: location doubtful

Disturbed

Regraded

Seeded

Released

Excluded

PreExisting

Prelaw

Bond Area

SITLA Mineral Leases

BLM Saleable Minerals

Community Pit
- Access

Mine

NonMine

Other

Interstate

US Route

State Route

Primary Route

Secondary Route


Main Dirt Road

Unimproved Road

Interchange

Trail

DOQ imagery date 2004



1:7,500 1 inch equals 625 feet
Verify Scale
Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.

Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program